


FIG. 1



2/7

**FIG. 4**

SCREEN1

Enter Employee or Contractor Number

Submit

FIG. 5

SCREEN2

1 Select a Module Module

2 Select a Process Module

3 Select a Cadre Cadre


Submit Cancel



Manager	Manager	Manager	Manager	Administrator	
Application Tools	Reports	Admin Tools			
In Training=IT		Expired Training=ET			
EMPLOYEE/ CONTRACTOR (#)	GENERAL LING READ	F COAT (LPT) 8100XP	LOLES LINE (COAT/E) (CR202 C)	COAT/DEV	AI INSPECT TACHI SEM IMENT OPER COAT/EXPOS TENCOR
ALLEN (00001)	C C	C	C C C C	C	C C C C C
ASHA (00002)	IT			IT	IT
BEAVER (00003)	C C		E+	C	C C
BUESHER (00004)	C C C C C C	C	AE AE AE	C	C C C C C
BRICKER (00005)	C		E	C	E E
CHEN (00006)	IT IT			IT	C C C IT C
ESTES (00007)	C C	IT	C C AE	C C AE AE	C IT
EVANS (00008)	IT			IT	IT
GARCIA (00009)	C C		C C		C C C C C
GILLEN (000010)	C			IT	C C C
HARRIS (000011)	C E			C	C AE C C
HILL (000012)	C C		C C C C		C C C
JENNINGS (000013)	E E	IT	C AE	C C C AE	
JIMENZ (000014)	C IT			C IT	C
KIMOTHO (000015)	IT IT		IT		
KOO (000016)	C IT			C C C	
MOODY (000017)	C C C IT	C C C C	C C C C C C	C C C C C C	
MORDI (000018)	C C	IT	C C C C	C C C C	
POE (000019)	IT IT			E C C	C
ROBERTS (000020)	C C		E E E	C E AE	E+
SEBASTIAN (000021)					
STOKER (000022)	IT IT		IT		
TIJERINA (000023)	C C	IT IT	C AE C C C C C		
WASHINGTON (000024)	C E			C C C	
WEHRMANN (000025)	IT IT			C C C	C
TOTAL	16	16	3 1 5 7 9 6 6	17 16 19 8	9
IT=INTRAINING E OR ET=EXPIRED TRAINING C=CERTIFIED					



FIG. 6





5/7

FIG. 7




FIG. 8




FIG. 9




FIG. 10






FIG. 11

